

Summary



REF: <u>J0Y10KFR</u> DATE: 08/08/2024

DEALER: Soldonmydrivecom Ltd

Vehicle History Check

MERCEDES-BENZ C180 SE BLUEEFFICIENCY AUTO SILVER, 2011



Minor issues

1	Plate Change Previous plate change
1	Road Tax and Sorn Flag exists on Tax & SORN
1	Taxi/PSV Check Not Checked
1	Recall Check Not Checked

All Clear

♦	Finance No finance agreement recorded
<	Mileage Reading No mileage discrepancies
<	At Risk No risk marker recorded
8	Write-Offs (MIAFTR) No write-off recorded
<	Condition Alerts No condition alerts
8	Scrapped Not scrapped, no VIC recorded
8	Stolen No stolen record

Description

VRM	КР11UTH	POWER	154 BHP
VEHICLE	MERCEDES-BENZ C180 SE BLUEEFFICIENCY AUTO	VALVES	4
ENGINE CC	1796 cc	GEARS	7
ENGINE SIZE	1.8 Litres	0-60 MPH	9 seconds
FUEL	PETROL	TOP SPEED	138 MPH
BODY	4 DOOR SALOON	LAST V5C	01/11/2023
TRANSMISSION	AUTOMATIC	DOORS	4
SEATS	5	BODY	SALOON
COLOUR	SILVER	BODY CLASS	CAR
REG DATE	27/06/2011	TYPE APPROVAL	M1
VIN	WDD2040492A562144	WHEEL PLAN	2 AXLE RIGID BODY
ENGINE NO.	27182030262232	BOOT CAPACITY	475 Litres
ENGINE CODE	M271 E18DE LA	REG CURRENT	N/A

Finance

FINANCE	No
LAST CHECKED ON	08/08/2024

Write Off (MIAFTR)

Condition Alerts


Scrapped

SCRAPPED	No
VIC	No

Stolen

STOLEN	No	

Mileages



DATE	READING	SOURCE		
Current Reading				
08/08/2024	51,000 Miles	SOLDONMYDRIVECOM LTD		
Historical R	Historical Readings			
06/02/2024	51,000 Miles	ADVERT		
21/09/2023	50,538 Miles	мот		
21/09/2022	46,093 Miles	МОТ		
07/10/2021	42,050 Miles	МОТ		
20/10/2020	38,854 Miles	МОТ		
29/05/2019	32,566 Miles	МОТ		
31/05/2018	28,487 Miles	МОТ		
30/05/2018	28,487 Miles	MOT		
05/06/2017	23,261 Miles	МОТ		
15/06/2016	19,331 Miles	МОТ		
23/06/2015	16,022 Miles	MOT		
02/06/2014	11,981 Miles	MOT		

Service History

At Risk

AT RISK

No

Taxi/PSV Check

Found 1 minor issue

FOUND ON TAXI/PSV DATABASE

Not Checked

Recall Check

Found 1 minor issue

RECALL OUTSTANDING

Not Checked

Keepers

PREVIOUS KEEPERS	2
AGE	13 years 1 month
AVG KEEPERS FOR AGE	5
LAST V5C	01/11/2023

KEEPER	START	FINISH	DURATION
Current	01/11/2023	N/A	9 months
2nd	16/05/2012	01/11/2023	11 years 5 months
1st	27/06/2011	16/05/2012	10 months

Plate Change

Found 1 minor issue

PLATE CHANGES Yes

REG	START	FINISH	DURATION
KP11UTH	22/09/2023	N/A	10 months
G2TGM	10/05/2012	22/09/2023	11 years 4 months
KP11UTH	27/06/2011	10/05/2012	10 months

Colour Change

COLOUR CHANGES No SILVER

Origin & Use

PRIOR USE	No
IMPORTED	No
IMPORTED NI	No
IMPORT DATE	N/A
ORIGIN	N/A

ORIGIN GERMANY

EXPORTED No

EXPORT DATE N/A

мот

MOT VALID	Yes
MOT EXPIRY	19/10/2024
REG DATE	27/06/2011
FIRST MOT DUE	01/06/2014

#1 21/09/2023 Pass

Test Date	21/09/2023
Expiry Date	19/10/2024
Odometer	50,538 Miles
Test No.	154910880459
Refusal Reason	N/A
Advisory	rear heatshield insecure. Offside Front Tyre slightly damaged/ cracking or perishing (5.2.3 (d) (ii)). unable to fully inspect underside of vehicle and sills due to covers. Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))
Minor	N/A

#3 21/09/2022 Pass

Test Date	21/09/2022
Expiry Date	19/10/2023
Odometer	46,093 Miles
Test No.	410625693262
Refusal Reason	N/A
Advisory	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)). Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). Offside Front Lower STICKER ON THE SCREEN. Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i)). Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)). Offside Front HEADLAMP AIM IS AT ITS LOWEST ACCEPITABLE LEVEL. Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i)). Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). PLASTIC FLOOR SILL AND ENGINE COVERS. Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)). ALL FOUR COIL SPRINGS ARE SLIGHTLY CORRODED. Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i)). Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). Nearside Front HEADLAMP AIM IS AT ITS HIGHEST ACCEPITABLE LEVEL. Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i)). Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)). ALL FOUR BRAKE DISCS ARE SLIGHTLY WORN
Minor	N/A

#2 21/09/2023

Fail

Test Date	21/09/2023
Expiry Date	N/A
Odometer	50,538 Miles
Test No.	903471750282
Refusal Reason	Offside Rear Outer Stop lamp(s) not working (4.3.1 (a) (ii))
Advisory	rear heatshield insecure. Offside Front Tyre slightly damaged/ cracking or perishing (5.2.3 (d) (ii)). unable to fully inspect underside of vehicle and sills due to covers. Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))
Minor	N/A

#4 21/09/2022 Fail

Test Date	21/09/2022
Expiry Date	N/A
Odometer	46,093 Miles
Test No.	561985124078
Refusal Reason	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Advisory	Offside Front Lower STICKER ON THE SCREEN. Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)). Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (ii)). Offside Front HEADLAMP AIM IS AT ITS LOWEST ACCEPITABLE LEVEL. Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i)). PLASTIC FLOOR SILL AND ENGINE COVERS. Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (ij)). Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)). Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (ii)). ALL FOUR COIL SPRINGS ARE SLIGHTLY CORRODED. Offside Front Brake hose slightly deteriorated (1.1.12 (b) (iii)). Nearside Front HEADLAMP AIM IS AT ITS HIGHEST ACCEPITABLE LEVEL. ALL FOUR BRAKE DISCS ARE SLIGHTLY WORN. Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (ii)). Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (ii)). Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (ii)). Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (iii)). Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (iii)). Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (iii)).
Minor	N/A

#5 07/10/2021 Pass

Test Date	07/10/2021
Expiry Date	19/10/2022
Odometer	42,050 Miles
Test No.	913425576680
Refusal Reason	N/A
Advisory	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)). Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)). BOTH FRONT HEADLAMP AIMS ARE AT THERE HIGHEST ACCEPITABLE LEVEL. Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). ALL FOUR COIL SPRINGS ARE SLIGHTLY CORRODED. Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)). Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (ii)). PLASTIC FLOOR SILL AND ENGINE COVERS. Offside Rear Tyre worn close to legal limit/worn on edge AT 2MM195/60/16 (5.2.3 (e)). Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (ii)). APPLIED FINGER AND THUMB PRESSURE ON SILLS AND FLOOR AREA
Minor	N/A

#6 20/10/2020 Pass

Test Date	20/10/2020
Expiry Date	19/10/2021
Odometer	38,854 Miles
Test No.	424545246239
Refusal Reason	N/A
Advisory	BOTH FRONT HEADLAMP AIMS ARE AT THERE HIGHEST ACCEPITABLE LEVEL. Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). PLASTIC FLOOR SILL AND ENGINE COVERS. Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)). Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)).
Minor	N/A

#7 29/05/2019

Test Date	29/05/2019
Expiry Date	27/12/2020
Odometer	32,566 Miles
Test No.	238173756459
Refusal Reason	N/A
Advisory	Nearside Front Brake pipe corroded, covered in grease or other material heavily corroded (1.1.11 (c)). Nearside Rear Brake pad(s) wearing thin and offside rear (1.1.13 (a) (ii)). service lamp indicates b service due. Nearside Front Brake disc worn, but not excessively and offside front (1.1.14 (a) (i)). Nearside Front Brake pad(s) wearing thin and offside front (1.1.13 (a) (ii)). front tyres worn unevenly
Minor	N/A

#8 31/05/2018

Pass

Test Date	31/05/2018
Expiry Date	27/06/2019
Odometer	28,487 Miles
Test No.	407437675519
Refusal Reason	N/A
Advisory	front brake discs lipped. o/s/r brake pipe starting to corrode (at securing clips). front brake pads getting low. both front tyres worn on shoulders
Minor	N/A
	·

#9 30/05/2018

Fail

Test Date	30/05/2018
Expiry Date	N/A
Odometer	28,487 Miles
Test No.	925926543744
Refusal Reason	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt thrust arm (5.3.4 (b) (ii)). Nearside Rear Brake pipe excessively corroded (1.1.11 (c)). Offside Front Suspension arm pin or bush likely to become detached bush separated from outer casing (5.3.4 (a) (ii)). Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt thrust arm (5.3.4 (b) (ii)). Offside Front Brake pipe excessively corroded (1.1.11 (c))
Advisory	front brake discs lipped. o/s/r brake pipe starting to corrode (at securing clips). front brake pads getting low. both front tyres worn on shoulders
Minor	N/A

#10 05/06/2017

Pass

Test Date	05/06/2017
Expiry Date	27/06/2018
Odometer	23,261 Miles
Test No.	276660090675
Refusal Reason	N/A
Advisory	N/A
Minor	N/A

09/08/2024, 10:44 6 of 11

#1

11 15/06/2016	Pass

Test Date	15/06/2016	
Expiry Date 27/06/2017		
Odometer	19,331 Miles	
Test No.	154659730389	
Refusal Reason	N/A	
Advisory Nearside Rear Tyre worn close to the legal limit (4.1.E.1 Offside Rear Tyre worn close to the legal limit (4.1.E.1		
Minor	N/A	

#12 23/06/2015 Pass

Test Date	23/06/2015	
Expiry Date 27/06/2016		
Odometer	16,022 Miles	
Test No.	867024375118	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#13 02/06/2014

Pass

Test Date	02/06/2014	
Expiry Date	27/06/2015	
Odometer	11,981 Miles	
Test No.	159133954170	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

Tax & SORN

Found 1 minor issue

TAX VALID	N/A
TAX EXPIRY	N/A
SORN	Yes

Valuation

8 of 11

PERCAYSO VALUATION

Valuation Based On 51,000 Miles as of 08/08/2024



Vehicle	Mercedes C Class
Trade Value	£4,080
Retail Value	£6,601
Supermarket Value	£6,366
Independent Value	£6,339
Franchise Value	£6,840

AUTOTRADER VALUATION

Today's Valuation Based On 51,000 Miles as of 08/08/2024



Mercedes-Benz C Class 1.8 C180 BlueEfficiency SE Saloon 4dr Petrol G-Tronic+ Euro 5 (s/s) (156 ps)
£3,610
£6,342
£3,510
£4,890
_

BREGO VALUATION

Valuation Based On 51,000 Miles as of 08/08/2024



VRM	KP11UTH
VIN	WDD2040492A562144

	HIGH	AVERAGE	LOW
Retail	£7,344	£6,715	£6,090
Trade	£5,907	£5,401	£4,898

Running Costs



^{*} The standard 12 month VED rate for all registered cars in this band is shown for the purposes of comparison. Note, figures quoted reflect the current rate only, and may be subject to change in the future. Cars with a list price of over £40,000 when new pay an additional rate of £310 per year on top of the standard rate, for five years

Warranty

	TOTAL PERIOD OR DISTANCE	REMAINING PERIOD	REMAINING DISTANCE
Whole Vehicle	36 Months / Unlimited	Expired	Valid
Powertrain	36 Months / Unlimited	Expired	Valid
Anti-Corrosion	360 Months / Unlimited	Valid	Valid
Paint	36 Months / Unlimited	Expired	Valid
Roadside Assistance	360 Months / Unlimited	Valid	Valid

FINANCE Finance Initial Check: 08/08/2024 11:08, No Finance 08/08/2024 Private KEEPERS Keepers Initial Check: 08/08/2024 11:08, 2 Previous Keepers found 08/08/2024 Private WRITE-OFF (MIAFTR)

MIAFTR Write-off Initial Check: 08/08/2024 11:08, No records found